

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Spring 2018 Levee Inspection Results

Plumas County

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
† Overall LMA Rating (Fall Only)				

** Non-receipt of Summer or Winter Inspection
Reports may effect overall annual rating.

† SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports. This rating is not intended to be an indication of risk.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2018 Levee Inspection Results

Plumas County

Waterway			Bank	Unit Miles
Unit No. 01 North Fork Feather River			Left	1.89
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/26/2018 - 4/26/2018			
DWR Inspector	Bob Duffey			
Accompanied By	Russell Furtado Plumas County Road Department			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start		Rating **	A	Issue No.	1
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Operations & Maintenance Manuals				
DWR ID	DWR_NA0015_01_s _ 2013_1				
Comment Code					
Inspector Comment					
The LMA has O&M manuals.					

No Photos

LM Start		Rating **	A	Issue No.	2
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Emergency Supplies & Equipment				
DWR ID	DWR_NA0015_01_s _ 2013_2				
Comment Code					
Inspector Comment					
The LMA has flood fight supplies and equipment.					

No Photos

LM Start		Rating **	M	Issue No.	3
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Flood Preparedness & Training				
DWR ID	DWR_NA0015_01_s _ 2013_3				
Comment Code					
Inspector Comment					
The LMA has not completed flood flight training in the last ten years.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.00	Rating **	C	Issue No.	11
LM End	0.78	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.273168 °	40.282842 °
				-121.244783 °	-121.251338 °
DWR ID	DWR_NA0015_01_f_2015_11				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The small pine trees and other vegetation was removed from the levee slope.					

No Photos

LM Start	0.00	Rating **	A	Issue No.	12
LM End	0.78	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.273168 °	40.282842 °
				-121.244783 °	-121.251338 °
DWR ID	DWR_NA0015_01_f_2015_12				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
The small pine trees and other vegetation was removed from the levee slope.					

Photo 1 of 2 : SP_2018_NA0015_337_12_20180501_00019.jpg



View of the removed pine trees and other vegetation from the waterside slope.

LM Start	0.00	Rating **	A	Issue No.	12 (cont)
LM End	0.78	Issue Type +	Ma	Location *	WS

Photo 2 of 2 : SP_2018_NA0015_337_12_20180305_00009.jpg



View of the small pine trees and other vegetation on the waterside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.01	Rating **	C	Issue No.	15
LM End	0.01	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.273274 °	40.273274 °
				-121.244779 °	-121.244779 °
DWR ID	DWR_NA0015_01_f _ 2016_15				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
The landside slope was repaired and new rocks was placed along the edge of the crown roadway.					

No Photos

LM Start	0.55	Rating **	C	Issue No.	9
LM End	0.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.279790 °	121.249850 °
				40.279790 °	121.249850 °
DWR ID	DWR_NA0015_01_s _ 2012_9				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
The waterside slope was repaired and new rocks was placed along the edge of the crown.					

No Photos

LM Start	0.68	Rating **	M	Issue No.	4
LM End	0.68	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.281480 °	40.281480 °
				-121.250928 °	-121.250928 °
DWR ID	DWR_NA0015_01_s _ 2013_4				
Comment Code					
PR : Prunings					
Inspector Comment					

Photo 1 of 1 : SP_2018_NA0015_337_4_20180305_00001.jpg



View of the prunings along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.77	Rating **	M	Issue No.	20
LM End	0.77	Issue Type +	En	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP Field Study			40.282683 °	40.282683 °
				-121.251453 °	-121.251453 °
DWR ID					
Comment Code					
Inspector Comment					
FS_ID:42643					
DS_ID:23039					
EP_NO: N/A					
Repair Type: Non-Urgent					
Crossing Status: Indicator Found					
UCIP Comments: Need to contact owner to determine additional information about crossing. Need depth of conduit and permit issued.					
FIELD_STRUCT_DESC: Telephone cable of an unknown size or material through the levee and across the channel, at an unknown depth. [Additional Reference(s): DWR Levee Log, 2005].					
FS Date: 11/4/2014					

LM Start	0.77	Rating **	M	Issue No.	20 (cont)
LM End	0.77	Issue Type +	En	Location *	

Photo 1 of 3 : UCIP_SP_2018_42643_72981.jpg



View of conduit pole located on landward side. Photo taken from right bank.

Photo 2 of 3 : UCIP_SP_2018_42643_72980.jpg



View of landward slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.77	Rating **	M	Issue No.	20 (cont)	
LM End	0.77	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			40.282683 °	40.282683 °	
				-121.251453 °	-121.251453 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:42643						
DS_ID:23039						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Need to contact owner to determine additional information about crossing. Need depth of conduit and permit issued.						
FIELD_STRUCT_DESC: Telephone cable of an unknown size or material through the levee and across the channel, at an unknown depth. [Additional Reference(s): DWR Levee Log, 2005].						
FS Date: 11/4/2014						


Photo 3 of 3 : UCIP_SP_2018_42643_72982.jpg



View of levee, ramp, and posts visible between trees.

LM Start	0.79	Rating **	M	Issue No.	18
LM End	1.88	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.282962 °	40.297068 °
				-121.251307 °	-121.257120 °
DWR ID	DWR_NA0015_01_s_2018_18				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the small pine trees and vegetation from the landside slope.					

Photo 1 of 1 : SP_2018_NA0015_337_18_20180501_00027.jpg



View of the small pine trees and vegetation along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.79	Rating **	M	Issue No.	19
LM End	1.88	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.282962 °	40.297068 °
				-121.251307 °	-121.257120 °
DWR ID	DWR_NA0015_01_s_2018_19				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the small pine trees and vegetation from the waterside slope.					

No Photos

LM Start	0.88	Rating **	M	Issue No.	13
LM End	0.88	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.284309 °	40.284309 °
				-121.251541 °	-121.251541 °
DWR ID	DWR_NA0015_01_f_2016_13				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the fallen tree from the levee slope.					

Photo 1 of 1 : SP_2018_NA0015_337_13_20180305_00010.jpg



View of the fallen tree on the landside slope.

LM Start	0.93	Rating **	C	Issue No.	10
LM End	0.93	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.284955 °	40.284955 °
				-121.251945 °	-121.251945 °
DWR ID	DWR_NA0015_01_f_2017_10				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
The waterside slope was repaired and new rocks were placed at the edge of the crown.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.96	Rating **	A/W	Issue No.	5
LM End	0.96	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.285363 °	40.285363 °
				-121.251973 °	-121.251973 °
DWR ID	DWR_NA0015_01_f_2013_5				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2018_NA0015_337_5_20180305_00002.jpg



View of the vehicle erosion along the waterside slope.

LM Start	1.04	Rating **	C	Issue No.	17
LM End	1.04	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.286302 °	40.286302 °
				-121.252233 °	-121.252233 °
DWR ID	DWR_NA0015_01_f_2017_17				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
The waterside slope was repaired and new rocks was place along the edge of the crown.					

No Photos

LM Start	1.05	Rating **	C	Issue No.	14
LM End	1.05	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.286337 °	40.286337 °
				-121.252460 °	-121.252460 °
DWR ID	DWR_NA0015_01_f_2017_14				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
The waterside slope was repaired and rocks was placed along the Edge of the crown.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	---	--	---	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start	1.17	Rating **	M	Issue No.	16
LM End	1.17	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.287722 °	40.287722 °
				-121.253510 °	-121.253510 °
DWR ID	DWR_NA0015_01_s_2017_16				
Comment Code					
TR : Tree or limb					
Inspector Comment					
Remove the tree from the landside slope and toe.					

Photo 1 of 1 : SP_2018_NA0015_337_16_20180305_00013.jpg



View of the tree along the landside slope and toe.

LM Start	1.41	Rating **	U	Issue No.	7
LM End	1.50	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.290758 °	40.291987 °
				-121.255402 °	-121.256072 °
DWR ID	DWR_NA0015_01_f_2014_7				
Comment Code					
MA : Material					
Inspector Comment					
The landowner needs to replace the material that has been removed from the toe of the levee.					

Photo 1 of 2 : SP_2018_NA0015_337_7_20180305_00003.jpg



View of the area where the contractor has removed the material from toe of the levee.

LM Start	1.41	Rating **	U	Issue No.	7 (cont)
LM End	1.50	Issue Type +	En	Location *	LS

Photo 2 of 2 : SP_2018_NA0015_337_7_20180305_00004.jpg



View of the area where the contractor has removed the material from toe of the levee.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	---	--	---	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 North Fork Feather River	Left	1.89	04/26/2018 04/26/2018	Bob Duffey

LM Start	1.86	Rating **	C	Issue No.	8
LM End	1.86	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.296910 °	40.296910 °
				-121.257280 °	-121.257280 °
DWR ID	DWR_NA0015_01_f_2014_8				
Comment Code					
TR : Tree or limb					
Inspector Comment					
The tree stumps was removed from the slope of the levee.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Spring 2018 Levee Inspection Results

Plumas County

Waterway			Bank	Unit Miles
Unit No. 02 North Fork Feather River			Right	1.36
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)				
Date of Inspection	4/26/2018 - 4/26/2018			
DWR Inspector	Bob Duffey			
Accompanied By	Russell Furtado Plumas County Road Department			

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.00	Rating **	M	Issue No.	2
LM End	0.71	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.286462 °	40.279948 °
				-121.260082 °	-121.252118 °
DWR ID	DWR_NA0015_02_f_2017_2				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the small pine trees and vegetation from the landside slope.					

Photo 1 of 1 : SP_2018_NA0015_338_2_20180305_00001.jpg



View of the small pine trees and vegetation along the landside slope.

LM Start	0.00	Rating **	M	Issue No.	3
LM End	0.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.286462 °	40.279948 °
				-121.260082 °	-121.252118 °
DWR ID	DWR_NA0015_02_f_2017_3				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Remove the small pine trees and vegetation from the waterside slope.					

Photo 1 of 1 : SP_2018_NA0015_338_3_20180305_00002.jpg



View other small pine trees and vegetation along the waterside slope.

LM Start	0.31	Rating **	C	Issue No.	9
LM End	0.31	Issue Type +	En	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Encroachments			40.284993 °	40.284993 °
				-121.255133 °	-121.255133 °
DWR ID	DWR_NA0015_02_s_2015_9				
Comment Code					
TR : Tree or limb					
Inspector Comment					
The pine trees was removed from the landside slope and toe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---	--	--	--	--	--

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.46	Rating **	M	Issue No.	6
LM End	0.46	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.283059 °	40.283059 °
				-121.253989 °	-121.253989 °
DWR ID	DWR_NA0015_02_f_2013_6				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

LM Start	0.46	Rating **	M	Issue No.	6 (cont)
LM End	0.46	Issue Type +	Ma	Location *	WS

Photo 1 of 2 : SP_2018_NA0015_338_6_20180305_00005.jpg



View of the vehicle erosion on the landside slope.

Photo 2 of 2 : SP_2018_NA0015_338_6_20180305_00006.jpg



View of the vehicle erosion on the waterside slope.

LM Start	0.55	Rating **	M	Issue No.	4
LM End	0.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.281950 °	121.253710 °
				40.281950 °	121.253710 °
DWR ID	DWR_NA0015_02_s_2012_4				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2018_NA0015_338_4_20180305_00003.jpg



View of the slope instability cause by vehicle along the landside slope.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.55	Rating **	M	Issue No.	5
LM End	0.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			40.281950 °	121.253710 °
				40.281950 °	121.253710 °
DWR ID	DWR_NA0015_02_s_2012_5				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					

Photo 1 of 1 : SP_2018_NA0015_338_5_20180305_00004.jpg



View of the vehicle erosion on the waterside slope.

LM Start	0.66	Rating **	M	Issue No.	10	
LM End	0.66	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			40.280737 °	40.280737 °	
				-121.252512 °	-121.252512 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:42644						
DS_ID:23040						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Need to contact owner to determine additional information about crossing. Need depth of conduit and permit issued.						
FIELD_STRUCT_DESC: Telephone cable of an unknown size or material through the levee and across the channel, at an unknown depth. [Additional Reference(s): DWR Levee Log, 2005].						
FS Date: 11/4/2014						

Photo 1 of 3 : UCIP_SP_2018_42644_72984.jpg



View of landward side conduit pole located at landward toe. Photo taken from the left bank.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	--	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.66	Rating **	M	Issue No.	10 (cont)	
LM End	0.66	Issue Type +	En	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start	End	
Item	DWR UCIP Field Study			40.280737 °	40.280737 °	
				-121.252512 °	-121.252512 °	
DWR ID						
Comment Code						
Inspector Comment						
FS_ID:42644						
DS_ID:23040						
EP_NO: N/A						
Repair Type: Non-Urgent						
Crossing Status: Indicator Found						
UCIP Comments: Need to contact owner to determine additional information about crossing. Need depth of conduit and permit issued.						
FIELD_STRUCT_DESC: Telephone cable of an unknown size or material through the levee and across the channel, at an unknown depth. [Additional Reference(s): DWR Levee Log, 2005].						
FS Date: 11/4/2014						

Photo 2 of 3 : UCIP_SP_2018_42644_72983.jpg



View of waterward side.

Photo 3 of 3 : UCIP_SP_2018_42644_72985.jpg



View of opposite bank.

LM Start	0.66	Rating **	M	Issue No.	10 (cont)
LM End	0.66	Issue Type +	En	Location *	

*** Location**

LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
 M : Minimally Acceptable C : Corrected
 U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Spring 2018

Plumas County

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 North Fork Feather River	Right	1.36	04/26/2018 04/26/2018	Bob Duffey

LM Start	0.71	Rating **	A	Issue No.	7
LM End	1.36	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.279948 °	40.271748 °
				-121.252118 °	-121.246737 °
DWR ID	DWR_NA0015_02_s _ 2018_7				
Comment Code					
V2 : Remove the wild growth other than native grasses from the levee slopes.					
Inspector Comment					
Small pine trees was removed from the landside slope.					

Photo 1 of 1 : SP_2018_NA0015_338_7_20180501_00013.jpg



View of the removed small pine trees from the landside slope.

LM Start	0.71	Rating **	A	Issue No.	8
LM End	1.36	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			40.279948 °	40.271748 °
				-121.252118 °	-121.246737 °
DWR ID	DWR_NA0015_02_s _ 2018_8				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
The small pine trees was removed from the waterside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
--	--	--	--	---	--	---	--